

Reliability Analysis – Now What?


Reliability Analysis – Now What?

#4



... this represents
time to failure (TTF)

the (random) hand of failure




time to failure (TTF)

the (random) hand of failure



time to failure (TTF)



40.73 %
probability of a loss




\$ 0.32
expected
profit

... but first ...
a little MCMC
revision

the
'classic' random walk
algorithm

this is the
likelihood function
based on the
Weibull distribution
as a model




β
shape parameter

n
scale parameter
(characteristic life)

computers can't

see


this shape




β
shape parameter

n
scale parameter
(characteristic life)


... random walking



... random walking
with bigger steps




... so we never explore all the
likelihood function




... random walking
with smaller steps



... then there is
SLICE SAMPLING






... randomly select a value within the likelihood

'height'

of our first point



β
shape parameter

... we use this randomly selected value to create our

slice


n
scale parameter
(characteristic life)

... but our computers
can only work in
rectangles
we define for them ...

... the next step is to
randomly
select a value
in our slice

... we use this randomly
selected value to create our


slice



n
scale parameter
(characteristic life)

... we can help make sure
our slice is in this rectangle
by making it

big




... we can help make sure
our slice is in this rectangle
by making it

big

... and we want to avoid


this



β
shape parameter


n
scale parameter
(characteristic life)


the rectangle of guess




... randomly
selecting points ...

... until we find one in our
slice!








... how much


better

is this!!!

slice sampling



Metropolis-
Hastings algorithm



let's do
this ...


1. Put your data in
2. Roughly estimate likely parameter values
3. Create a log likelihood function
4. (... if you want) find the MLE
5. Create slice sampling widths
6. SAMPLE!
7. Use those samples

1. Put your data in

the (random) hand of failure



time to failure (TTF)




MATLAB

```
t =  
[ ... all your  
observed  
times to failure  
... ]
```



```
t = matrix(  
+ c(... all your  
observed times to  
failure ...)  
+ nrow = ?  
+ ncol = ?)
```

2. Roughly estimate
likely parameter
values





```
beta0 =  
[log(log(n + 0.4)-log(n - 0.3))-  
log(log(n + 0.4)-log(0.1))] ...  
/ ...  
(log(t1)-log(tn))
```



MATLAB



```
eta0 =  
exp(log(t1) + ...  
((log(1) - log(log(n + 0.4) -  
log(0.1)))) / beta0))
```

3. Create a log
likelihood
function



```
>> logL0 = @(p) ...  
    log(p(2)) + ...  
sum((p(2)-1).*log(t)) - ...  
(p(2)*log(p(1))) - ...  
sum((t./p(1)).^ p(2))  
  
>> option = ...  
{logL0 @(p) -Inf}  
  
>> logL = @(p) ...  
option{1 + (min(p) <= 0)}(p)
```




```
logLik <- function(eta ,  
                    beta , t) {  
  + if(eta <= 0 || beta <=0  
      ) {  
  + result = -Inf}  
  + if (eta > 0 && beta > 0) {  
  + result = log(beta) +  
  sum((beta-1)*log(t)) -  
  (beta*log(eta)) -  
  sum((t./eta)^ beta) } }
```

4 . (... if you want)
find the MLE


5. Create slice sampling widths

... we can help make sure
our slice is in this rectangle
by making it


big




the rectangle of guess



... randomly
selecting points ...




... randomly
selecting points ...



... randomly
selecting points ...

... until we find one in our
slice!




... so let's try

3

times our initial
parameter
estimates


... randomly
selecting points ...



... randomly
selecting points ...


... and we want to avoid


this




... so what does

chris do?







6 . SAMPLE !



```
p =  
slicesample ...  
([eta0 , beta0] , ...  
10000 , ...  
'logpdf' , logL , ...  
'width' , 3 * [eta0 , beta0])
```



```
p <- mcmc(logL,  
c(eta0 , beta0) ,  
10000 ,  
3 * (eta0 , beta0))
```

*... find and research your
own package!*

p =

... each row contains the parameters of a **sampled Weibull distribution**

... this column contains the scale parameters (η)	1.3126	1.8121
	1.2381	2.1264
	1.172	2.0913
	0.7563	1.9265
	1.1949	1.9385
	1.1358	1.6517
	0.8186	1.9352
	0.895	1.8561
	0.8963	1.8714
	0.9315	1.8856
	0.9353	1.721
	0.8678	1.4534
	0.8218	1.4308
	0.8126	1.3933

... this column contains the **shape** parameters (β)




... and there are **1000** rows (or samples) in total


... just a random
guess at where
to start

```
p = ... no estimate for  
      rectangle width  
  
slicesample ...  
([1, 1], ..., ...  
10000, ..., ...  
'pdf', ..., ...  
@ (p) prod(wblpdf(x, p(1), p(2))))
```


... didn't use the
log-likelihood

probability of failure





7. Use those samples



MATLAB

F =

```
wblcdf(2,p(:,1),p(:,2))
```




F =

```
1-exp(-((2/p(:,1))^p(:,2)))
```


F =

0.0325
0.0205
0.0245
0.0742
0.0308
0.0552
0.0633
0.0601
0.0586
0.0535
0.0679
0.1117
0.124
0.1322

... each row contains a
sampled
failure probability
at 2 years



our
100
samples
of
reliability
at 2 years



probability of (warranty period) failure


warrantyCost =
F * 115

warrantyCost =

\$ 3.74
\$ 2.36
\$ 2.81
\$ 8.53
\$ 3.54
\$ 6.35
\$ 7.28
\$ 6.91
\$ 6.74
\$ 6.15
\$ 7.81
\$ 12.85
\$ 14.26
\$ 15.20

... each row contains a

sampled
warranty cost




profit =
10 - warrantyCost


profit =

... each row contains a

sampled
profit

\$	6.26
\$	7.64
\$	7.19
\$	1.47
\$	6.46
\$	3.65
\$	2.72
\$	3.09
\$	3.26
\$	3.85
\$	2.19
-\$	2.85
-\$	4.26
-\$	5.20





40.73 %
probability of a loss



... so what
is next?

... go and turn

DATA

... into

INFORMATION

