Fred Schenkelberg Fundamentals of Process Capability







How do you use process capability?

What is Process Capability?







A Stable Process

What is PC?

A valid Capability Index requires a stable process.

In-control, monitored, improved

Yes, I mean Statistical Process Control

This creates the required nominal and variation information



Target & Tolerances

What is PC?

The measured features are often noted on a drawing.

Target or optimum

with tolerance(s)



A Ratio

What is PC?

The spread of the specified tolerance limits

over the spread of the stable process



Whichindex

do you use?

Various Indices







Cp Various Indices

$$C_p = \frac{(USL - LSL)}{6\hat{\sigma}}$$



Cpk

Various Indices

$$C_{\mathsf{pk}} = \min\left(\frac{\mathsf{USL} - \bar{x}}{3\hat{\sigma}}, \frac{\bar{x} - \mathsf{LSL}}{3\hat{\sigma}}\right)$$



Others

Various Indices

Prototype parts (adjust the variance calculation)

Off-center target from tolerance


Non-normal distributions




How have you seen

seen PC go wrong?

Not really Process Capability







Lack of Stability Not really PC

Faulty control chart process

Poor assumptions

Assume stability - no measure

Use theoretical values

No active monitoring for out of control situations



Tolerance Issues

Not really PC

Tight tolerances, production methods, and costs

Plus/Minus 10%

Critical dimensions lacking tolerances




Selection & Monitoring Not really PC

Vendor supplies generic Cpk, doesn't have tolerances

Unnecessarily high Cpk targets

No monitoring and updates to process values

No updates to Cpk calculations when design tolerances change



What is working for

your organization?

Additional Comments and Questions

Thanks

see more at AccendoReliability.com