


wait until the valve cover is off to adjust it.

Edit: the tick is louder on the serpentine side and did try to push down on the baffle, but it wouldn't move. Will have to



 $http://forums.genvibe.com/phpBB3/viewtopic.php?f=11\&t=45178\#p512306[12/28/2016\ 1:56:10\ PM]$