

SELLER'S PROPERTY DISCLOSURE STATEMENT EXHIBIT " _____ "



2025 Printing

This Seller's Property Disclosure Statement ("Statement") is an exhibit to the Purchase and Sale Agreement with an Offer Date of _____ for the Property (known as or located at: 1379 LITTLE HENDRICKS MOUNTAIN RD JASPER, Georgia, 30143). This Statement is intended to make it easier for Seller to fulfill Seller's legal duty to disclose hidden defects in the Property of which Seller is aware. Seller is obligated to disclose such defects even when the Property is being sold "as-is."

A. INSTRUCTIONS TO SELLER IN COMPLETING THIS STATEMENT.

In completing this Statement, Seller agrees to:

- (1) answer all questions in reference to the Property and the improvements thereon;
- (2) answer all questions fully, accurately and to the actual knowledge and belief of all Sellers (hereinafter, collectively "Knowledge");
- (3) provide additional explanations to all "yes" answers in the corresponding Explanation section below each group of questions (including providing to Buyer any additional documentation in Seller's possession), unless the "yes" answer is self-evident;
- (4) promptly revise the Statement if there are any material changes in the answers to any of the questions prior to Closing and provide a copy of the same to the Buyer and any Broker involved in the transaction.

B. HOW THIS STATEMENT SHOULD BE USED BY BUYER. Caveat emptor or "buyer beware" is the law in Georgia. Buyer should conduct a thorough inspection of the Property. If Seller has not occupied the Property or has not recently occupied the Property, Seller's Knowledge of the Property's condition may be limited. Buyer is expected to use reasonable care to inspect the Property and confirm that it is suitable for Buyer's purposes. If an inspection of the Property reveals problems or areas of concern that would cause a reasonable Buyer to investigate further, Buyer should investigate further. A "yes" or "no" answer to a question means "yes" or "no" to the actual Knowledge and belief of all Sellers of the Property. In other words, if a Seller answers "no" to a question, it means Seller has no Knowledge whether such condition exists on the Property. As such, Seller's answers should not be taken as a warranty or guaranty of the accuracy of such answers, nor a substitute for Buyer doing its own due diligence.

C. SELLER DISCLOSURES.

	YES	NO
1. GENERAL:		
(a) What year was the main residential dwelling constructed? <u>1994</u>	<input type="checkbox"/>	<input type="checkbox"/>
(b) Is the Property vacant? If yes, how long has it been since the Property has been occupied? _____	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(c) Is the Property or any portion thereof leased?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(d) Has the Property been designated as historic or in a historic district where permission must be received to make modifications and additions?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
EXPLANATION: _____ _____		
2. COVENANTS, FEES, and ASSESSMENTS:		
(a) Is the Property subject to a recorded Declaration of Covenants, Conditions, and Restrictions ("CC&Rs") or other similar restrictions?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
(b) Is the Property part of a condominium or community in which there is a community association? IF YES, SELLER TO COMPLETE AND PROVIDE BUYER WITH A "COMMUNITY ASSOCIATION DISCLOSURE EXHIBIT" GAR F322.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
EXPLANATION: _____ _____		
3. LEAD-BASED PAINT:		
(a) Was any part of the residential dwelling on the Property or any painted component, fixture, or material used therein constructed or manufacture prior to 1978? IF YES, THE "LEAD-BASED PAINT EXHIBIT" GAR F316 MUST BE EXECUTED BY THE PARTIES AND THE "LEAD-BASED PAINT PAMPHLET" GAR CB04 MUST BE PROVIDED TO THE BUYER.	<input type="checkbox"/>	<input checked="" type="checkbox"/>

4. STRUCTURAL ITEMS, ADDITIONS AND ALTERATIONS:	YES	NO
(a) Has there been any settling, movement, cracking or breakage of the foundations or structural supports of the improvements?		<input checked="" type="checkbox"/>
(b) Have any structural reinforcements or supports been added?	<input checked="" type="checkbox"/>	
(c) Have there been any additions, structural changes, or any other major alterations to the original improvements or Property, including without limitation pools, carports or storage buildings?		<input checked="" type="checkbox"/>
(d) Has any work been done where a required building permit was not obtained?		<input checked="" type="checkbox"/>
(e) Are there violations of building codes, housing codes, or zoning regulations (not otherwise grandfathered)?		<input checked="" type="checkbox"/>
(f) Have any notices alleging such violations been received?		<input checked="" type="checkbox"/>
(g) Is any portion of the main dwelling a mobile, modular or manufactured home?		<input checked="" type="checkbox"/>
(h) Was any dwelling or portion thereof (excluding mobile, modular and manufactured dwelling) moved to the site from another location?		<input checked="" type="checkbox"/>

EXPLANATION: (b) Deck board separated and was reattached (nailed), joist hangers installed on entire deck, angle ties installed in corners, and railing resecured. (September, 2014)

5. SYSTEMS and COMPONENTS:	YES	NO
(a) Has any part of the HVAC system(s) been replaced during Seller's ownership?	<input checked="" type="checkbox"/>	
(b) Date of last HVAC system(s) service: <u>July 2024</u>		
(c) Is any heated and cooled portion of the main dwelling not served by a central heating and cooling system?		<input checked="" type="checkbox"/>
(d) Is any portion of the heating and cooling system in need of repair or replacement?		<input checked="" type="checkbox"/>
(e) Does any dwelling or garage have aluminum wiring other than in the primary service line?		<input checked="" type="checkbox"/>
(f) Are any fireplaces decorative only or in need of repair?		<input checked="" type="checkbox"/>
(g) Have there been any reports of damaging moisture behind exterior walls constructed of synthetic stucco?		<input checked="" type="checkbox"/>
(h) Is there any Spray Polyurethane Foam (SPF) insulation in the Property?		<input checked="" type="checkbox"/>
(i) Are any systems/components subject to a lease or rental payment plan (i.e. HVAC, security system, appliances, alternate energy source systems, etc.)?		<input checked="" type="checkbox"/>
(j) Are there any remotely accessed thermostats, lighting systems, security camera, video doorbells, locks, appliances, etc. servicing the Property?		<input checked="" type="checkbox"/>

EXPLANATION: New Lennox Heat Pump was installed in October 2019. (5. a)

6. SEWER/PLUMBING RELATED ITEMS:	YES	NO
(a) Approximate age of water heater(s): <u>27</u> years		
(b) What is the drinking water source: <input type="checkbox"/> public <input checked="" type="checkbox"/> private <input type="checkbox"/> well		
(c) If the drinking water is from a well, give the date of last service: _____		
(d) If the drinking water is from a well, has there ever been a test the results of which indicate that the water is not safe to drink? If yes, date of testing: _____		
(e) What is the sewer system: <input type="checkbox"/> public <input type="checkbox"/> private <input checked="" type="checkbox"/> septic tank		
(f) If the Property is served by a septic system, how many bedrooms was the septic system approved for by local government authorities? <u>3</u>		
(g) Is the main dwelling served by a sewage pump?		<input checked="" type="checkbox"/>
(h) Has any septic tank or cesspool on Property ever been professionally serviced? If yes, give the date of last service: _____		<input checked="" type="checkbox"/>
(i) Are there any leaks, backups, or other similar problems with any portion of the plumbing, water, or sewage systems or damage therefrom?		<input checked="" type="checkbox"/>
(j) Is there presently any polybutylene plumbing, other than the primary service line?		<input checked="" type="checkbox"/>
(k) Has there ever been any damage from a frozen water line, spigot, or fixture?		<input checked="" type="checkbox"/>

EXPLANATION:

7. ROOFS, GUTTERS, and DOWNSPOUTS:		YES	NO
(a)	Approximate age of roof on main dwelling: <u>10</u> years.		
(b)	Has any part of the roof been repaired during Seller's ownership?		<input checked="" type="checkbox"/>
(c)	Are there any roof leaks or other problems with the roof, roof flashing, gutters, or downspouts?		<input checked="" type="checkbox"/>

EXPLANATION:

8. FLOODING, DRAINING, MOISTURE, and SPRINGS:		YES	NO
(a)	Is there now or has there been any water intrusion into the basement, crawl space or other interior parts of any dwelling or garage or damage therefrom from the exterior?	<input checked="" type="checkbox"/>	
(b)	Have any repairs been made to control water intrusion into the basement, crawl space, or other interior parts of any dwelling or garage from the exterior?	<input checked="" type="checkbox"/>	
(c)	Is any part of the Property or any improvements thereon presently located in a Special Flood Hazard Area?		<input checked="" type="checkbox"/>
(d)	Has there ever been any flooding?		<input checked="" type="checkbox"/>
(e)	Are there any streams that do not flow year round or underground springs?		<input checked="" type="checkbox"/>
(f)	Are there any dams, retention ponds, storm water detention basins, or other similar facilities?		<input checked="" type="checkbox"/>

EXPLANATION: *Excessive rain in a short time frame caused the gutter above back deck to overflow into the attic. Attic inspection revealed no water damage. A downspout was installed to expedite drainage, and there has been no overflow since this installation. (2014)*

9. SOIL AND BOUNDARIES:		YES	NO
(a)	Are there any landfills (other than foundation backfill), graves, burial pits, caves, mine shafts, trash dumps or wells (in use or abandoned)?		<input checked="" type="checkbox"/>
(b)	Is there now or has there ever been any visible soil settlement or movement?		<input checked="" type="checkbox"/>
(c)	Are there any shared improvements which benefit or burden the Property, including, but not limited to a shared dock, septic system, well, driveway, alleyway, or private road?		<input checked="" type="checkbox"/>
(d)	Are there presently any encroachments, unrecorded easements, unrecorded agreements regarding shared improvements, or boundary line disputes with a neighboring property owner?		<input checked="" type="checkbox"/>
(e)	Are there any underground pipelines crossing the Property that do not serve the Property?		<input checked="" type="checkbox"/>

EXPLANATION:

10. TERMITES, DRY ROT, PESTS, and WOOD DESTROYING ORGANISMS:		YES	NO
(a)	Are you aware of any wildlife accessing the attic or other interior portions of the residence?	<input checked="" type="checkbox"/>	
(b)	Is there any damage or hazardous condition resulting from such wildlife intrusion; from insects (such as termites, bees and ants); or by fungi or dry rot?		<input checked="" type="checkbox"/>
(c)	Is there presently a bond, warranty or service contract for termites or other wood destroying organisms by a licensed pest control company?		<input checked="" type="checkbox"/>
If yes, what is the cost to transfer? \$ _____ What is the annual cost? _____			
If yes, company name/contact: _____			
Coverage: <input type="checkbox"/> re-treatment and repair <input type="checkbox"/> re-treatment <input type="checkbox"/> periodic inspections only			
Expiration Date _____ Renewal Date _____			

EXPLANATION: *1) HVAC ductwork to two front bedrooms was damaged by rodents (field mice). New metal ducts were built at the house and installed. Mice were exterminated. Due to no airflow in front bedrooms for an unknown amount of time some mold was observed primarily in closets and cabinets. Mold was removed and there has been no recurrence since HVAC system was repaired. (July 2024)*

(continued in "Additional Explanations")

11. ENVIRONMENTAL, HEALTH, and SAFETY CONCERNS:	YES	NO
(a) Are there any underground tanks or toxic or hazardous substances such as asbestos?		<input checked="" type="checkbox"/>
(b) Has Methamphetamine ("Meth") ever been produced on the Property?		<input checked="" type="checkbox"/>
(c) Have there ever been adverse test results for radon, lead, mold or any other potentially toxic or environmentally hazardous substances?		<input checked="" type="checkbox"/>

EXPLANATION:

12. LITIGATION and INSURANCE:	YES	NO
(a) Is there now or has there been any litigation therein alleging negligent construction or defective building products?		<input checked="" type="checkbox"/>
(b) Has there been any award or payment of money in lieu of repairs for defective building products or poor construction?		<input checked="" type="checkbox"/>
(c) Has any release been signed regarding defective products or poor construction that would limit a future owner from making any claims?		<input checked="" type="checkbox"/>
(d) During Seller's ownership have there been any insurance claims for more than 10% of the value of the Property?		<input checked="" type="checkbox"/>
(e) Is the Property subject to a threatened or pending condemnation action?		<input checked="" type="checkbox"/>
(f) How many insurance claims have been filed during Seller's ownership?		<input checked="" type="checkbox"/>

EXPLANATION:

13. OTHER HIDDEN DEFECTS:	YES	NO
(a) Are there any other hidden defects that have not otherwise been disclosed?		<input checked="" type="checkbox"/>

EXPLANATION:

14. AGRICULTURAL DISCLOSURE:	YES	NO
(a) Is the Property within, partially within, or adjacent to any property zoned or identified on an approved county land use plan as agricultural or forestry use?		<input checked="" type="checkbox"/>
(b) Is the Property receiving preferential tax treatment as an agricultural property?		<input checked="" type="checkbox"/>

It is the policy of this state and this community to conserve, protect, and encourage the development and improvement of farm and forest land for the production of food, fiber, and other products, and also for its natural and environmental value. This notice is to inform prospective property owners or other persons or entities leasing or acquiring an interest in real property that property in which they are about to acquire an interest lies within, partially within, or adjacent to an area zoned, used, or identified for farm and forest activities and that farm and forest activities occur in the area. Such farm and forest activities may include intensive operations that cause discomfort and inconveniences that involve, but are not limited to, noises, odors, fumes, dust, smoke, insects, operations of machinery during any 24-hour period, storage and disposal of manure, and the application by spraying or otherwise of chemical fertilizers, soil amendments, herbicides, and pesticides. One or more of these inconveniences may occur as the result of farm or forest activities which are in conformance with existing laws and regulations and accepted customs and standards.

ADDITIONAL EXPLANATIONS (If needed):

- Item 10 A continued:
- 2) Old, limited termite damage was found by repairman 2020-2021, in pink bedroom under windows near the floor. This was repaired and there has been no recurrence here or anywhere else in the house since.
 - 3) In 2009 pine beetle infestation was found in exterior siding at the left end of house. The damaged siding was removed, insects exterminated and Hardie-Plank siding was installed on the left front left end and screened porch. There has been no recurrence since that time.
 - 4) In 2016 the master bath picture window was repaired, caulked, and painted due to damage from car porter ants. Ants were exterminated at that time and there has been no re-infestation.

D. FIXTURES CHECKLIST

1. **Directions on How to Generally Fill Out Fixtures Checklist.** REGARDLESS OF WHETHER AN ITEM IS A FIXTURE OR NOT, SELLER SHALL HAVE THE RIGHT TO REMOVE ALL ITEMS ON THE FIXTURES CHECKLIST BELOW THAT ARE LEFT BLANK. THE ITEMS ON THE CHECKLIST BELOW THAT ARE CHECKED OR MARKED SHALL REMAIN WITH THE PROPERTY. Unless otherwise indicated, if an item is left blank, the Seller may remove all of that item from the Property. For example, if "Refrigerator" is left blank, Seller shall remove all Refrigerators on the Property, unless otherwise noted. Similarly, if "Refrigerator" is checked or marked in the Fixtures Checklist, then all refrigerators shall remain with the Property unless otherwise noted. This Fixtures Checklist is intended to supersede the common law of fixtures with regard to the items identified below. The common law of fixtures shall apply to all items not identified on this Fixtures Checklist.
2. **Items Not Remaining with the Property.** Items identified as not remaining with the Property that are physically attached to the Property shall be carefully removed from the Property in a manner designed to do minimal damage, but such items do not need to be replaced with a similar item. Seller shall make reasonable efforts to repair areas damaged by the removal of an item. Reasonable efforts to repair damage shall not extend to painting newly exposed areas that do not match the surrounding paint color. (Seller is encouraged, but shall not be required, to remove fixtures not remaining with the Property prior to marketing the Property for sale). Seller shall remove all items left blank below prior to Closing or the transfer of possession, whichever is later. Seller shall lose the right to remove those items not timely removed but shall be liable to Buyer for the reasonable cost of disposing such items provided that Buyer disposes of them within 30 days after Closing or the transfer of possession, which is later.
3. **Items Remaining with Property.** Items identified as remaining with the Property shall mean those specific items, including any solely necessary or required controller, as they existed in the Property as of the Offer Date. No such item shall be removed from the Property unless it is broken or destroyed. In the event such item is removed, it shall be replaced with a substantially identical item, if reasonably available. If not reasonably available, it shall be replaced with a substantially similar item of equal quality and value, or better. The same or newer model of the item being replaced in the same color and size and with the same functions or

better shall be considered substantially identical. Once the Seller's Property is under contract, the items that may be removed and taken by the Seller, as reflected in this Seller's Property Disclosure Statement, may only be amended with the written consent of the Buyer of the Property.

Appliances

- Clothes Dryer
- Clothes Washing Machine
- Dishwasher
- Garage Door Opener
- Garbage Disposal
- Ice Maker
- Microwave Oven
- Oven
- Range
- Refrigerator w/o Freezer
- Refrigerator/Freezer
- Free Standing Freezer
- Surface Cook Top
- Trash Compactor
- Vacuum System
- Vent Hood
- Warming Drawer
- Wine Cooler

Home Media

- Amplifier
- Cable Jacks
- Cable Receiver
- Cable Remotes
- Intercom System
- Internet HUB
- Internet Wiring
- Satellite Dish
- Satellite Receiver
- Speakers
- Speaker Wiring
- Switch Plate Covers

- Television (TV)
- TV Antenna
- TV Mounts/Brackets
- TV Wiring

Interior Fixtures

- Ceiling Fan
- Chandelier
- Closet System
- Fireplace (FP)
- FP Gas Logs
- FP Screen/Door
- FP Wood Burning Insert
- Light Bulbs
- Light Fixtures
- Mirrors
 - Wall Mirrors
 - Vanity (hanging) Mirrors
- Shelving Unit & System
- Shower Head/Sprayer
- Storage Unit/System
- Window Blinds (and Hardware)
- Window Shutters (and Hardware)
- Window Draperies (and Hardware)
- Unused Paint

Landscaping / Yard

- Arbor
- Awning
- Basketball Post and Goal

- Birdhouses
- Boat Dock
- Fence - Invisible
- Dog House
- Flag Pole
- Gazebo
- Irrigation System
- Landscaping Lights
- Mailbox
- Out/Storage Building
- Porch Swing
- Statuary
- Stepping Stones
- Swing Set
- Tree House
- Trellis
- Weather Vane

Recreation

- Aboveground Pool
- Gas Grill
- Hot Tub
- Outdoor Furniture
- Outdoor Playhouse
- Pool Equipment
- Pool Chemicals
- Sauna

Safety

- Alarm System (Burglar)
- Alarm System (Smoke/Fire)
- Security Camera
- Carbon Monoxide Detector
- Doorbell
- Door & Window Hardware

- Fire Sprinkler System
- Gate
- Safe (Built-In)
- Smoke Detector
- Window Screens

Systems

- A/C Window Unit
- Air Purifier
- Whole House Fan
- Attic Ventilator Fan
- Ventilator Fan
- Car Charging Station
- Dehumidifier
- Generator
- Humidifier
- Propane Tank
- Propane Fuel in Tank
- Fuel Oil Tank
- Fuel Oil in Tank
- Sewage Pump
- Solar Panel
- Sump Pump
- Thermostat
- Water Purification System
- Water Softener System
- Well Pump

Other

- All Furniture (Werner) not staying
- 6' silver ladder
- All kitchen items
- All pictures and wall hangings

Clarification Regarding Multiple Items. Items identified above as remaining with Property where Seller is actually taking one or more of such items shall be identified below. For example, if "Refrigerator" is marked as staying with the Property, but Seller is taking the extra refrigerator in the basement, the extra refrigerator and its location shall be described below. This section shall control over any conflicting or inconsistent provisions contained elsewhere herein.

All items in crawl space, with the exception of the blue ladder galvanized trash cans roofing shingles and misc. various hand tools and paint will not remain with the house. Clothing and bed linen will not remain with the property. wheelbarrow outside the back of the house will not remain with property.

Items Needing Repair. The following items remaining with Property are in need of repair or replacement:

I cannot find the key to side door.

RECEIPT AND ACKNOWLEDGEMENT BY BUYER

Buyer acknowledges receipt of this Seller's Property Disclosure Statement.

SELLER'S REPRESENTATION REGARDING THIS STATEMENT

Seller represents that the questions in this Statement have been answered to the actual knowledge and belief of all Sellers of the Property

1 Buyer's Signature

Print or Type Name

Date

2 Buyer's Signature

Print or Type Name

Date

Additional Signature Page (F267) is attached.

Pamela P. Schildecker

1 Seller's Signature

Pamela P. Schildecker

Print or Type Name

7/29/25

Date

2 Seller's Signature

Print or Type Name

Date

Additional Signature Page (F267) is attached.

DISCLOSURE OF PAST ISSUES AT 1379 LITTLE HENDRICKS MOUNTAIN ROAD
July 29, 2025

1. 2009: Pine beetle infestation occurred on the left end of house. Damaged siding and insulation were removed and insects exterminated. New Hardee Plank siding was installed in the left front section of house and the left end of the house, as well as screened porch. There has been no evidence of infestation since that time (*Item 17, repair document*).
2. 2014: The deck railing separated from the deck (*Item 15, repair document*). The deck band separation was corrected and lag bolted and joist hangers and corner fasteners installed. No problems have been encountered since that time.
3. 2018-2019: There were two instances of heavy downpours in a short amount of time that caused the gutter behind the living room area over deck to overflow into the attic. A subsequent attic inspection found no water damage. There is evidence of the overflow into the master bedroom back right corner, as it hasn't been repainted. A downspout was installed in the valley between the living room and the screened porch and there has been no overflow since that time (*Item 14, repair document*).
4. 2020-2021: My repairman noticed, coincidental with other repairs, termite signs near the floor under the windows in the pink bedroom. This old infestation was confined to a small area and repaired, and there has been no recurrence since that time. This is not noted on his invoices.
5. July 2024: Rodents invaded the crawl space at an unknown time, tearing insulation, damaging ductwork, and hampering airflow in the front two bedrooms. The old ductwork and associated trash were removed and new metal ducts, built on site, were installed. The rodents (field mice) were exterminated, and airflow has been excellent since that time (*Item 1, repair document*).
6. Due to impairment of the HVAC system (see above) for an undetermined amount of time, sporadic mold growth occurred in the house, primarily confined to areas with poor air flow such as closets and cabinets. Mold was removed promptly after HVAC repair and there has been no regrowth.

Submitted by:
Pamela P. Schildecker
Owner

RECORD OF REPAIRS AND MAINTENANCE

1379 Little Hendricks Mountain Road
October 2002 to July 23, 2025

1. July 2024: The HVAC System, installed in October of 2019, failed to cool in July of 2024, and after several service calls, the condenser coil was replaced under warranty. During this time, the two front bedrooms were found failing to blow air. A technician removed several concrete blocks to access these two bedrooms, which were walled off in the crawl space, and found that rodents had severely damaged the ductwork, severing one completely. New metal ductwork was built on-site and installed, at which time the system began functioning very well. All debris was removed, and rodents were exterminated.
2. June 2024: New screens were installed on the back porch to replace ones that were torn due to improper material and installation.
3. June 2024: New window glass was installed (1 pane) in the left front bedroom due to fogging.
4. February 2024: All new exterior light fixtures and new screened porch ceiling fan were installed.
5. May 2021: A new side door in kitchen/dining area was installed.
6. June 2020, May 2021: The back porch was rescreened in 2020, then repaired in 2021.
7. June 2020: A new wooden porch floor was installed and painted on screened porch due to rotting boards under previously installed ceramic tile.
8. February 2019: Fifteen dead, diseased, and trees threatening house were removed.
9. October 2019: A new HVAC system was installed.
10. August 2018: New glass for one sliding door in living area and the master bath picture window were installed due to fogging.
11. May 2016: Master bath picture window was repaired, caulked and painted due to carpenter ant damage.
12. May 2016: Master toilet was serviced.
13. December 2014: Deck was prepped and painted with Deckover paint.
14. December 2014: A downspout was installed between the living area and screened porch in the back roof valley to prevent overflow in heavy rains.
15. September 2014: Deck was jacked where separated, outer deck band lag bolted, joist hangers installed on entire deck, angle ties installed in corners, and railing resecured to remedy separation.
16. ~2009: New attic ventilating turbine was installed (receipt not dated).
17. 2009: Removed damaged siding and trim on left front and left end of house due to pine beetle infestation. This was replaced with Hardee Plank.
18. February 2008: Screened porch floor was replaced with ceramic tile.
19. January 2008: HVAC system was repaired (faulty defrost controls).
20. August 2009: A new roof was installed using 30-year architectural shingles; an 80-ft. ridge vent was also installed. The old roof was removed.
21. October 2005: New gas logs were purchased and installed.
22. October 2002: Polybutylene plumbing was removed from house and copper pipes installed as a condition of my purchase.
23. Several miscellaneous repairs, maintenance, painting, etc., were made during my ownership of the house.

*File with all receipts included has been maintained and is available.