



... what is probability plotting?


human beings are good at identifying straight lines in things ...








human beings are good at identifying straight lines in things ...


... but not different curves



































probability plotting

... a graphical technique for comparing two data sets.

... typically one 'empirical' data set which could be the observed times to failure on a reliability demonstration test ... and one 'theoretical' set like a set of vandom variables described by a normal, lognormal, Weibull, ... distribution


probability plotting papers

... scaled and for a specific probability distribution

If plotted data creates a straight line, it suggests that the underlying random process is described by the specific probability distribution

21


probability plotting papers





... and the most popular probability plotting paper is the one based on the Weibull distribution


23


... starting with being able to estimate distribution parameters directly from our probability plot






















the 8 steps for probability plotting


33

... are the subject of a specific lesson



... and we can find different failure modes on one chart!







... but don't try and see things that aren't there ...

39

... let's say our system has three components




... let's say our system has three components





41

... so let's simulate failures of this system





... so let's compare this to a bathtub curve with a lower hazard rate







... and again











... Weibull analysis just the beginning – you need to understand why failures are occurring

... this is a problem if we are using the Weibull distribution for servicing or preventive maintenance (PM) intervals...







... so by doing less preventive maintenance (PM) we improved reliability by 23 %.


... but don't try and see things that aren't there ...


57





... but don't try and see things that aren't there especially at small CDF values












... always understand the uncertainty or the 'confidence' we have on our results


65


... and the confidence on the results?




... your confidence increases as you have more data or information


... but most commercial software makes a tonne of assumptions





... it gets worse for the less information you have





... do you know what assumptions your probability plotting software makes?

