SERVICE PARTS LIST

Milwaukee

Collar Spring

Spindle Returning Spring


48


49

40-50-1575

40-50-1640

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS DATE REVISED BULLETIN Nov. 2013 18 Volt PEX Expander WIRING INSTRUCTION





WIRING SPECIFICATIONS				
Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation
1	Red			Connect to the positive terminal on motor and 'M1' on switch.
2	Black			Connect to the negative terminal on motor and 'M2' on switch.
3	Red	23-66-2935		Component of the switch assembly. Attached to connector block and switch.
4	Black	23-66-2935		Component of the switch assembly. Attached to connector block and PCB assembly.
5	Red	23-66-2935		Part of the switch assy. One of a 5 wire harness that plugs into PCB assy. Other end soldered with #3 to connector block.
6	Blue	23-66-2935		Part of the switch assy. One of a 5 wire harness that plugs into PCB assy. Other end soldered to connector block.
7	Black	23-66-2935		Part of the switch assy. One of a 5 wire harness that plugs into PCB assy. Other end soldered to connector block.
8	Blue	23-66-2935		Component of the switch assy. Wires #8 and #9 are part of a 5 wire harness that plugs into the PCB assy. #8 and #9 are sleeved together and connect to the LED at the other end.
9	Yellow	23-66-2935		
10	Orange	23-66-2935		Part of the switch assy. One of a 4 wire harness that plugs into PCB assy. Other end attached to the switch.
11	White	23-66-2935		Part of the switch assy. One of a 4 wire harness that plugs into PCB assy. Other end attached to the switch.
12	Green	23-66-2935		Part of the switch assy. One of a 4 wire harness that plugs into PCB assy. Other end attached to the switch.
13	Brown	23-66-2935		Part of the switch assy. One of a 4 wire harness that plugs into PCB assy. Other end attached to the switch.
14	Blue	23-66-2935		Component of the switch assembly. Attached to switch and PCB assembly.