



NOTES:

1. BE SURE INDEXING PINS ARE INSTALLED AND ORIENTED TO ACCOMMODATE YOUR DESIRED MOUNTING.
2. THE HANDLE/STEM REPAIR KIT FOR THIS MODEL IS: 5452HST.
3. THE VALVE REPAIR KIT FOR THIS MODEL IS: 5800VRKT.



**REPLACEMENT PARTS
AVAILABLE**



1455 KLEPPE LANE
SPARKS, NEVADA 89431
(775) 359-4712 FAX (755) 359-7424
E-MAIL: HAWS@HAWS.CO.COM
WEBSITE: WWW.HAWS.CO.COM

ECN NO. REVISED PER BY:	MODEL(S)	5452LF	PART NUMBER	0002074495
3936 ECN 4514 SLS			DRAWING NO.	12933A00
DRAWN: DATE: CHD			REV	5
DO 387			SIZE	A
APPROVED: DATE: 10/24/12			DRAWING TYPE	INSTALLATION
			SCALE	1/2
			SHEET	1 OF 1