

PROPERTY LOCATED AT: 5 HARRY STREET, YORK, ME 03909

### PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.**

#### SECTION I – WATER SUPPLY

TYPE OF SYSTEM:  Public  Private  Seasonal N/A  Unknown  
 Drilled  Dug  Other N/A

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): .....  N/A  Yes  No  Unknown  
Quantity: .....  Yes  No  Unknown  
Quality: .....  Yes  No  Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? .....  Yes  No  
If Yes, Date of most recent test: OCT 2013 Are test results available? ..  Yes  No  
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? .....  Yes  No  
If Yes, are test results available? .....  Yes  No  
What steps were taken to remedy the problem? UV SYSTEM INSTALLED IN 2013

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: BACK RIGHT CORNER AT END OF PARKING AREA  
Installed by: UNKNOWN  
Date of Installation: 1981+/-

USE: Number of persons currently using system: 2  
Does system supply water for more than one household?  Yes  No  Unknown

Comments: NEW WELL PUMP INSTALLED IN 2009 BY PREVIOUS OWNERS

Source of Section I information: SELLER, PREVIOUS OWNERS

Buyer Initials \_\_\_\_\_ Page 1 of 7 Seller Initials TOH ALA

PROPERTY LOCATED AT: 5 HARRY STREET, YORK, ME 03909

**SECTION II – WASTE WATER DISPOSAL**

TYPE OF SYSTEM:  Public  Private  Quasi-Public N/A  Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

~~Have you had the sewer line inspected?.....  Yes  No~~

~~If Yes, what results: N/A~~

~~Have you experienced any problems such as line or other malfunctions? .....  Yes  No~~

~~What steps were taken to remedy the problem? N/A~~

IF PRIVATE (Strike Section if Not Applicable):

Tank:  Septic Tank  Holding Tank  Cesspool  Other: N/A

Tank Size:  500 Gallon  1000 Gallon  Unknown  Other: N/A

Tank Type:  Concrete  Metal  Unknown  Other: N/A

Location: IN FRONT OF DECK OR  Unknown

Date installed: UNK Date last pumped: SEPT 2013 Name of pumping company: A-1 ENVIRONMENTAL

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem: N/A

Date of last servicing of tank: SEPT 2013 Name of company servicing tank: A-1 ENVIRONMENTAL

Leach Field: .....  Yes  No  Unknown

If Yes, Location: FRONT YARD IN FRONT OF DECK

Date of installation of leach field: 1976+/- Installed by: UNKOWN

Date of last servicing of leach field: N/A Company servicing leach field: N/A

Have you experienced any malfunctions? .....  Yes  No

If Yes, give the date and describe the problem and what steps were taken to remedy: N/A

Do you have records of the design indicating the # of bedrooms the system was designed for?  Yes  No

If Yes, are they available? .....  Yes  No

Is System located in a Shoreland Zone? .....  Yes  No  Unknown

Comments: A-1 ENVIRONMENTAL CLEANED OUT SOME ROOT INTRUSION THAT WAS IDENTIFIED DURING INSPECTION IN 2013

Source of Section II information: SELLER

Buyer Initials \_\_\_\_\_

Seller Initials TOH ALT



PROPERTY LOCATED AT: 5 HARRY STREET, YORK, ME 03909

What materials are, or were, stored in the tank(s)? N/A

Have you experienced any problems such as leakage: .....  Yes  No  Unknown

Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF UNDERGROUND STORAGE TANKS ON THE PROPERTY

Source of information: SELLER; PREVIOUS OWNERS DISCLOSURE

**B. ASBESTOS** — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? .....  Yes  No  Unknown

In the ceilings? .....  Yes  No  Unknown

In the siding? .....  Yes  No  Unknown

In the roofing shingles? .....  Yes  No  Unknown

In flooring tiles? .....  Yes  No  Unknown

Other: N/A  Yes  No  Unknown

Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF ASBESTOS ON THE PROPERTY

Source of information: SELLER; PREVIOUS OWNERS DISCLOSURE

**C. RADON/AIR** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: N/A By: N/A

Results: N/A

If applicable, what remedial steps were taken? N/A

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF RADON/WATER AND HAS NEVER TESTED

Source of information: SELER; PREVIOUS OWNERS DISCLOSURE

**D. RADON/WATER** - Current or previously existing:

Has the property been tested? .....  Yes  No  Unknown

If Yes: Date: N/A By: N/A

Results: N/A

If applicable, what remedial steps were taken? N/A

Has the property been tested since remedial steps? .....  Yes  No  Unknown

Are test results available? .....  Yes  No

Results/Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF RADON/WATER AND HAS NEVER TESTED

Source of information: SELLER; PREVIOUS OWNERS DISCLOSURE

**E. METHAMPHETAMINE** - Current or previously existing:

Yes  No  Unknown

Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF METHAMPHETAMINE USE ON TEH PROPERTY

Source of information: SELLER

Buyer Initials \_\_\_\_\_

Seller Initials

<sup>DS</sup>  
TCH

<sup>DS</sup>  
ALH

PROPERTY LOCATED AT: 5 HARRY STREET, YORK, ME 03909

**F. LEAD-BASED PAINT/PAINT HAZARDS** — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? .....  
.....  Yes  No  Unknown  Unknown (but possible due to age)

If Yes, describe location and basis for determination: N/A

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards:  Yes  No

If Yes, describe: N/A

Are you aware of any cracking, peeling or flaking paint? .....  Yes  No

Comments: ALL INTERIOR NEWLY PAINTED IN 2019; ALL NEW ANDERSON WINDOWS AND EXTERIOR DOORS IN 2015/16

Source of information: SELLER; PREVIOUS OWNERS DISCLOSURE

**G. OTHER HAZARDOUS MATERIALS** - Current or previously existing:

TOXIC MATERIAL: .....  Yes  No  Unknown

LAND FILL: .....  Yes  No  Unknown

RADIOACTIVE MATERIAL: .....  Yes  No  Unknown

Other: SELLER HAS NO PERSONAL KNOWLEDGE OF HAZARDOUS MATERIALS ON THE PROPERTY

Source of information: SELLER; PREVIOUS OWNERS DISCLOSURE

**Buyers are encouraged to seek information from professionals regarding any specific issue or concern.**

**SECTION V — GENERAL INFORMATION**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? .....  Yes  No  Unknown

If Yes, explain: ROW OVER HEMLOCK TO HARRY STREET

Source of information: SELLER; DEED

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? .....  Yes  No  Unknown

If No, who is responsible for maintenance? ROAD ASSOCIATION (ROAD AGREEMENT AVAILABLE)

Road Association Name (if known): TBHH SOUTH ROAD ASSOCIATION

Buyer Initials \_\_\_\_\_

Seller Initials TAH ALA

PROPERTY LOCATED AT: 5 HARRY STREET, YORK, ME 03909

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....  
.....  Yes  No  Unknown

If Yes, explain: N/A

Is a Forest Management and Harvest Plan available?.....  Yes  No  Unknown

Is house now covered by flood insurance policy (not a determination of flood zone)  Yes  No  Unknown

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: NONE

Year Principal Structure Built: 1976: NEW DECK IN 2013

What year did Seller acquire property? 2013

Roof: Year Shingles/Other Installed: NEW ROOF AND SKYLIGHTS IN 2014

Water, moisture or leakage: NONE

Comments: DECK WAS RESTAINED IN 2018; CEDAR SIDING WAS SEAL COATED IN 2019

Foundation/Basement:

Is there a Sump Pump? .....  Yes  No  Unknown

Water, moisture or leakage since you owned the property: .....  Yes  No  Unknown

Prior water, moisture or leakage? .....  Yes  No  Unknown

Comments: NONE

Mold: Has the property ever been tested for mold? .....  Yes  No  Unknown

If Yes, are test results available? .....  Yes  No

Electrical:  Fuses  Circuit Breaker  Other: N/A  Unknown

Comments: NEW ELECTRIC BASEBOARD HEAT INSTALLED IN 2013

Has all or a portion of the property been surveyed? .....  Yes  No  Unknown

If Yes, is the survey available? .....  Yes  No  Unknown

Manufactured Housing – Is the residence a:

Mobile Home .....  Yes  No  Unknown

Modular .....  Yes  No  Unknown

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: SELLER HAS NO PERSONAL KNOWLEDGE OF MATERIAL DEFECTS ON THE PROPERTY

Comments: NONE

Source of Section V information: SELLER

PROPERTY LOCATED AT: 5 HARRY STREET, YORK, ME 03909

**SECTION VI – ADDITIONAL INFORMATION**

**42 TREES CUT DOWN/STUMPS REMOVED (2014); NEW ROOF AND SKYLIGHTS (2014); NEW SIDING (2015); ALL NEW WINDOWS & EXTERIOR DOORS (2015/16); NEWLY POURED CONCRETE UNDER HOUSE WITH STORAGE SPACE ADDED (2016); GUTTERS INSTALLED (2018); 2 MINI SPLITS WITH A/C (2019); NEW FLOORS (2019); NEW KITCHEN/BATH (2019); DECK STAINED IN 2018. CEILINGS & WALLS REDONE (2018); NEW APPLIANCES (2019)**

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: .....  Yes  No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:  
Tristan O. Halloran 3/29/2021  
SELLER DATE  
TRISTAN O. HALLORAN

DocuSigned by:  
Angellee L.C. Halloran 3/29/2021  
SELLER DATE  
ANGELLEE L.C. HALLORAN

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE

