

CYPRESS GROVE MAINTENANCE SCHEDULE

DATE	DESCRIPTION	VENDOR	COMPLETE
8/10/2018	Railing, #121	PBM Const	x
8/10/2018	Hanging tree branch outside front of #144	Tree Man	x
8/10/2018	Have gardeners clear tree debris under cypress tree at entrance	Vista LS	x
8/10/2018	RFP pickleball striping	Vintage Contractors	x 10/20/2018
8/13/2018	RFP Carlisle PVC membrane roof system	Nobel Roofing	x Contract accepted. Start date 12/3, weather permitting
10/21/2018	Tree branch reported fallen on garage roof #130	The Tree Man	Removed 10/23/18
11/28/2018	Pole light out at far end of tennis crt, near #125	Peter Cepeda	x
11/29/2018	Tree branches down near #124 & #128	Vista LS	