MONTANA WELL LOG REPORT

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Other Options

Return to menu Plot this site in State Library Digital Atlas Plot this site in Google Maps View scanned well log (5/19/2010 2:18:27 PM)

Site	Name:	CLANCY	PATRICK I	
OILG	Maille.	CEMILO	PAINON	_

GWIC Id: 170595

Section 1: Well Owner(s)

1) CLANCY, PATRICK L. (MAIL) **RR1 YELLOWSTONE MEADOWS** PARK CITY MT 59063 [06/07/1998]

Section 2: Location

Township	Range	Section	Quarter Sections
028	23E	34	SE¼ SW¼ SW¼
	County		Geocode

STILLWATER

Latitude	Longitude	Geomethod	Datum
45.611301	-108.8802	TRS-SEC	NAD83

Addition **Block** Lot YELLOWSTONE MEADOWS

Section 3: Proposed Use of Water

IRRIGATION (1) STOCKWATER (2)

Section 4: Type of Work

Drilling Method: CABLE Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Sunday, June 7, 1998

Section 6: Well Construction Details

Borehole dimensions From To Diameter 0 23.5

Casing

			Pressure	Wall			
e	ıt Type	Joint	Rating	Thickness	Diameter	То	From
B STEEL	A53B			0.25	6	23	-2
,B 2	IND3E			U.25	6 /5	23	-2

Completion (Perf/Screen)

				Size of	
From	To	Diameter	Openings	Openings	Description
23	23	6			OPEN BOTTOM

Annular Space (Seal/Grout/Packer)

Aima	<u> </u>	pago (Coan Croas		
			Cont.	
From	То	Description	Fed?	
0	21	#8 CASING SEAL		

Section 7: Well Test Data

Total Depth: 23

Static Water Level: 8.08 Water Temperature:

Pump Test *

Depth pump set for test 23 feet.

40 gpm pump rate with 3 feet of drawdown after _ hours of pumping.

Time of recovery 0.25 hours. Recovery water level 8.08 feet. Pumping water level 11 feet.

Ground Surface Altitude Ground Surface Method Datum Date * During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.

Section 8: Remarks

Section 9: Well Log Geologic Source

110ALVM - ALLUVIUM (QUATERNARY)

TIDALVINI - ALLOVIONI (QUATERNART)				
From	То	Description		
0	1	TOPSOIL		
1	4	GRAVEL SAND & CLAY		
4	23	GRAVEL & SAND W/CLAY SILTS		
23	23.5	SHALE		

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: MARVIN W. JEWETT Company: A-1 DRILLING/BILLINGS DRILLING License No: WWC-532 6/7/1998