Colo Lori

PROPERTY LOCATED AT: 4 HEMMING WAY, YORK, ME 03909

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

	SECTION I - WATER SUPPLY	
TYPE OF SYSTE	M: Public X Private Seasonal N/A Unknown X Drilled Dug Other N/A	
MALFUNCTION	Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?	
	Pump (if any): No X Unknown Quantity: Yes No X Unknown	
	Quality:	
WATER TEST:	Have you had the water tested? X Yes No f Yes, Date of most recent test: 03/31/2025 Are test results available? X Yes No Fo your knowledge, have any test results ever been reported as unsatisfactory Yes X Yes No or satisfactory with notation? Yes Yes Yes No f Yes, are test results available? X Yes No What steps were taken to remedy the problem? NONE Yes No)
IF PRIVATE: (Stri	te Section if Not Applicable):	
INSTALLATIO	N: Location: FROM GARAGE END OF HOUSE, RIGHT SIDE OF PROPERTY Installed by: UNKNOWN Date of Installation: 1989	_
USE:	Number of persons currently using system: <u>0</u> Does system supply water for more than one household? Yes X No Unknow	/n
Comments: <u>NEW WEL</u>	PUMP IN 2015 & PRESSURE TANK IN 2021; PH (SECONDARY TEST) WAS SLIGHTLY ELEVATED AT 8.73 (SUGGESTED LIMIT IS 8.5)	
Source of Section I Buyer Initials	information: SELLER, PUBLIC RECORD, PREVIOUS DISCLOSURE	_
iwell Banker Yorke Realty, 529 US Ro lyn K. Barrett, Broker	te 1, Suite 101 York ME 03909 Phone: 2073371515 Fax: 2073631458 RUST FAM Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com	пга

PROPERTY LOCATED AT: <u>4 HEMMING WAY, YORK, ME 03909</u>
SECTION II - WASTE WATER DISPOSAL
TYPE OF SYSTEM: X Public Private Quasi-Public N/A Unknown
IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable): Have you had the sewer line inspected?
If Yes, what results: <u>N/A</u>
Have you experienced any problems such as line or other malfunctions?
What steps were taken to remedy the problem? <u>N/A</u>
IF PRIVATE (Strike Section if Not Applicable):
Tank: Septic Tank Holding Tank Cesspool Other:
Tank Size 500 Gallon 🗌 1000 Gallon 🗌 Unknown 🗌 Other:
Tank Type: Concrete Metal Unknown Other:
Location:OR Unknown
Location: OR Unknown Date installed: Date last pumped: Name of pumping company:
Have you experienced any malfunctions?
Date of last servicing of tank:None of company servicing tank:
Leach Field:
If Yes, Location:
Date of installation of least field:Installed by:
Date of last servicing of leach field:Company servicing leach field:
Have you experienced any malfunctions?
If Yes, give the date and describe the problem and what steps were taken to remedy:

Do you have records of the design indicating the # of bedrooms the system was designed for?	Yes No
If Yes, are they available?	L Yes
Is System located in a Shoreland Zone? Ves 🗌 No [Unknown
Comments: PROPERTY SERVICED BY YORK PUBLIC SEWER DEPARTMENT	
Source of Section II information: SELLER, PUBLIC RECORD	

Buyer Initials _____ ___

Page 2 of 8

Initial **JDR**t Seller Initials

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Heating System(s) or Source(s) SYSTEM 1 SYSTEM 2 SYSTEM 3 SYSTEM 4 TYPE(S) of System FHW-BASEBOARD	SE	CTION III - HEATIN	NG SYSTEM(S)/HE	ATING SOURCE(S	5)		
TYPE(S) of System FIRE BASEBOARD Age of system(s) or source(s) 2007 '/- TYPE(S) of Fael OIL Annual consumption per system or source (i.e., galons, kilowatt bours.conds) 2013: 783 GAL Name of company that services yORK OIL system(s) or source(s) 2024: 1,011 GAL Name of company that services yORK OIL system(s) or source(s) yORK OIL source (i.e., galons, kilowatt 2024: 1,011 GAL Malfunctions per system(s) or source(s) NONE KNOWN source(s) within past 2 years NONE KNOWN Other pertinent information *ANNUAL CLEANING Are there fuel supply lines?							
Age of system(s) or source(s) 2007 +/- TYPE(S) of Fuel OIL Annual consumption per system 2023 - 783 CAL around consumption per system 203 - 783 CAL around consumption per system YORK OIL Date of most recent service call 322825* Mafinactions per system(s) or source(s) within past 2 years NONE KNOWN Other pertinent information *ANNUAL CLEANING Are there fuel supply lines? X Yes No Unknown Yes No Unknown Are there fuel supply lines? X Yes No Unknown Are there fuel supply lines? X Yes No Unknown Are there fuel supply lines? X Yes No Unknown Are there fuel supply lines? X Yes No Unknown Are there fuel supply lines? Yes No Unknown If Yes, are they lined? Yes No Unknown Is more than one heat source vented through one flu			51516,412	010111010	01010411		
Annul consumption per system or source (i.e., gallons, kilowatt hours, cerds) 2023: 783 GAL 2024: 1,011 GAL Name of company that services system(s) or source(s) YORK OIL Date of most recent service call 328/25* Muffinctions per system(s) or source(s) within past 2 years NONE KNOWN Other pertinent information *ANNLAL CLEANING Are there fuel supply lines?							
or source (i.e., gallons, kilowatt 2023: 783 GAL hours, cords) 2024: LOH GAL Name of company that services? YORK OIL system(s) or source(s) YORK OIL system(s) or source(s) YORK OIL Malfunctions per system(s) or source(s) within past 2 years NONE KNOWN Other perinent information *ANNUAL CLEANING Are there fuel supply lines? XNOVE KNOWN Are any buried? Yes No Unknown If Yes, are they lined: Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown If Yes, ate: N/A Date chimney(s) last cleaned: 2016(PREY. OWNER) Direct/Power Vent(s): Yes	TYPE(S) of Fuel	OIL					
or source (i.e., galions, klowatt hours, cords) 2024: 1,011 GAL Name of compary that services system(5) or source(5) YORK OIL Date of most recent service call 3/28/25* Miffunctions per system(5) or source(5) NONE KNOWN Other pertinent information *ANNUAL CLEANING Are there fuel supply lines? No Are there fuel supply lines? Yes No Yes No Yes No Unknown Are there fuel supply lines? Yes No Unknown Are any buried? Yes No Unknown If Yes, are they lined: Yes No Unknown Has chimney(s) been inspected? Yes Date chimney(s) last cleaned: 2016(PREY, OWNER) Direct/Power Vent(s): NA Direct/Power Vent(s): NA Direct/Power Vent(s): NA <tr< td=""><td></td><td>2023: 783 GAL</td><td></td><td></td><td></td></tr<>		2023: 783 GAL					
Name of company that services system(s) or source(s) YORK OIL System(s) or source(s) 328/25* Mafinetions per system(s) or source(s) within past 2 years NONE KNOWN Other periment information *ANNUAL CLEANING Are there fuel supply lines?							
system(s) or source(s) VORK OIL Date of most recent service call 3/28/25* Matfunctions per system(s) NONE KNOWN source(s) within past 2 years NONE KNOWN Other pertinent information *ANNUAL CLEANING Are there fuel supply lines?							
Malfunctions per system(s) or source(s) within past 2 years NORE KNOWN Other pertinent information *ANNUAL CLEANING Are there fuel supply lines? ````````````````````````````````````		YORK OIL					
source(s) within past 2 years NORE KNOWN Other pertinent information *ANNUAL CLEANING Are there fuel supply lines? X Yes No Unknown Yes Are any buried? Yes Yes No Unknown Are any buried? Yes Yes No Unknown Are all sleeved? Yes Yes No Unknown Chimney(s): Yes No Unknown If Yes, are they lined: Yes No Unknown Had a chimney (s): Yes No Unknown Had a chimney (s) been inspected? Yes Direct/Power Vent(s): N/A Direct/Power Vent(s) been inspected? Yes Direct/Power Vent(s) been inspected? Yes No Unknown Has vent(s) been inspected? Yes No Unknown If Yes, date: N/A Comments: WOODSTOVE HOOKUP IN KITCHEN, CONDITION UNKNOWN AS SELLER NEVER USED IT <t< td=""><td>Date of most recent service call</td><td>3/28/25*</td><td></td><td></td><td></td></t<>	Date of most recent service call	3/28/25*					
Source(s) winnip last 2 years *ANNUAL CLEANING Other pertinent information *ANNUAL CLEANING Are there fuel supply lines? Yes No Unknown Are any buried? Yes No Unknown Are any buried? Yes Yes No Unknown Yes Are all sleeved? Yes Yes No Unknown Chimney(s): Yes No Unknown If Yes, are they lined: Yes No Unknown Is more than one heat source vented through one flue? Yes Yes No Unknown Has chimney(s) been inspected? Yes No Date chimney(s) last cleaned: 2016(PREV. OWNER) Direct/Power Vent(s):		NONE KNOWN					
Are there fuel supply lines? No Unknown Are any buried? Yes No Unknown Are all sleeved? Yes No Unknown Are all sleeved? Yes No Unknown Are all sleeved? Yes No Unknown Chimney(s): Yes No Unknown If Yes, are they lined: Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown Had a chimney(s) been inspected? Yes No Unknown Has chimney(s) been inspected? Yes No Unknown If Yes, date: N/A Yes No Unknown Comments: WOODSTOVE HOOKUP IN KITCHEN, CONDITION UNKNOWN AS SELLER							
Are any buried? Yes No Unknown Are all sleeved? No Unknown Are all sleeved? No Unknown Chimney(s): Yes No Unknown If Yes, are they lined: Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown Had a chimney fire: Yes No Unknown Has chimney(s) been inspected? Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, date: N/A Yes No X Unknown Has vent(s) been inspected? Yes No X Unknown Has vent(s) been inspected? Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, are tanks in current use? Yes No	Other pertinent information	*ANNUAL CLEANING					
Are any buried? Yes No Unknown Are all sleeved? No Unknown Are all sleeved? No Unknown Chimney(s): Yes No Unknown If Yes, are they lined: Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown Had a chimney fire: Yes No Unknown Has chimney(s) been inspected? Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, date: N/A Yes No X Unknown Has vent(s) been inspected? Yes No X Unknown Has vent(s) been inspected? Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, are tanks in current use? Yes No	Are there fuel supply li	nec?		Ves	No Unknown		
Are all sleeved? X Yes No Unknown Chimney(s): X Yes No Unknown If Yes, are they lined: X Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown Had a chimney fire: Yes No Unknown Has chimney(s) been inspected? Yes No X Unknown If Yes, date: N/A No X Unknown Date chimney(s) last cleaned: 2016(PREV. OWNER) No X Unknown Has vent(s) been inspected? Yes No X Unknown Has vent(s) been inspected? Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, date: N/A Yes No X Unknown Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL Yes No X Unknown <td< td=""><td></td><td></td><td></td><td>_</td><td></td></td<>				_			
Chimney(s): X Yes No If Yes, are they lined: X Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown Had a chimney fire: Yes No Unknown Had a chimney(s) been inspected? Yes No Unknown If Yes, date: N/A No Unknown Date chimney(s) last cleaned: 2016(PREV. OWNER) No Unknown Has vent(s) been inspected? Yes No Unknown Has vent(s) been inspected? Yes No Unknown If Yes, date: N/A Ves No Unknown Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property?							
If Yes, are they lined: If Yes, are they lined: If Yes, are they lined: If Yes, if Yes No Unknown Is more than one heat source vented through one flue? Yes No Unknown Had a chimney (s) been inspected? Yes No Unknown Has chimney(s) been inspected? Yes No Unknown If Yes, date: NA Yes No Unknown If Yes, date: N/A Yes No Unknown Has vent(s) been inspected? Yes No Unknown Has vent(s) been inspected? Yes No Unknown Has vent(s) been inspected? Yes No Unknown If Yes, date: N/A Yes No Unknown If Yes, date: N/A Yes No Unknown If Yes, date: N/A Yes No Unknown Source of Section III information: SELLER, PREVIOUS DISCLOSURE Section III information: Section III information: Yes No Winknown A UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No<							
Is more than one heat source vented through one flue?							
Had a chimney fire:							
Has chimney(s) been inspected? Yes No Unknown If Yes, date: N/A Date chimney(s) last cleaned: 2016(PREV. OWNER) Direct/Power Vent(s): No Unknown Has vent(s) been inspected? Yes No Unknown If Yes, date: N/A Yes No Unknown Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown If Yes, are tanks in current use? Yes No Unknown If Yes, are tanks in current use, have tanks been abandoned according to DEP? Yes No Unknown If no longer in use, have tanks been abandoned according to DEP? Yes No Muknown Age of tank(s): N/A Size of tank(s): N/A							
If Yes, date: N/A Date chimney(s) last cleaned: 2016(PREV. OWNER) Direct/Power Vent(s): X Yes No Unknown Has vent(s) been inspected? Yes Yes No X Yes No X Yes, date: N/A Comments: WOODSTOVE HOOKUP IN KITCHEN, CONDITION UNKNOWN AS SELLER NEVER USED IT Source of Section III information: SELLER, PREVIOUS DISCLOSURE Section III information: SELLER, PREVIOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes Yes No X Unknown Yes, are tanks in current use? Yes If to longer in use, how long have they been out of service? No Yes No X If tanks are no longer in use, have tanks been abandoned according to DEP? Yes If tanks registered with DEP? Size of tank(s): No Age of tank(s): NA Size of tank(s): Location:<							
Date chimney(s) last cleaned: 2016(PREV. OWNER) Direct/Power Vent(s): Masses Has vent(s) been inspected? Yes No Yes Yes Yes Yes Yes No Yes No Yes No Yes Yes No Yes No Yes No Yes No Yes No Yes	Has chimney(s) been inspected? Ves Ves No X Unknown						
Direct/Power Vent(s): X Yes No Unknown Has vent(s) been inspected? Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, date: N/A Yes No X Unknown If Yes, date: N/A Yes No X Unknown Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No X Unknown If Yes, are tanks in current use? Yes No X Unknown If no longer in use, how long have they been out of service? N/A Yes No X Unknown Are tanks registered with DEP? Size of tank(s): N/A Yes No X Unknown Age of tank(s): N/A Size of tank(s): N/A Yes No X Unknown	If Yes, date: <u>N/A</u>						
Has vent(s) been inspected?	Date chimney(s) last	cleaned: 2016(PREV. 0	OWNER)				
If Yes, date: N/A Comments: WOODSTOVE HOOKUP IN KITCHEN, CONDITION UNKNOWN AS SELLER NEVER USED IT Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? If Yes, are tanks in current use? Yes No Yunknown If no longer in use, how long have they been out of service? N/A If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Yunknown Are tanks registered with DEP? Size of tank(s): N/A Yes No Yunknown Age of tank(s): N/A Size of tank(s): N/A Yes No Yunknown	Direct/Power Vent(s):			X Yes	No Unknown		
Comments: WOODSTOVE HOOKUP IN KITCHEN, CONDITION UNKNOWN AS SELLER NEVER USED IT Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? If Yes, are tanks in current use? Yes No No Unknown If no longer in use, how long have they been out of service? N/A Yes No No Unknown Are tanks registered with DEP? Size of tank(s): N/A No Unknown Age of tank(s): N/A Size of tank(s): N/A No X Unknown							
Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? If Yes, are tanks in current use? Yes No Yunknown If no longer in use, how long have they been out of service? N/A If tanks are no longer in use, have tanks been abandoned according to DEP? Yes Yes No Yunknown Are tanks registered with DEP? Size of tank(s): N/A Location: NONE KNOWN							
Source of Section III information: SELLER, PREVIOUS DISCLOSURE SECTION IV - HAZARDOUS MATERIAL The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? If Yes, are tanks in current use? Yes No Yunknown If no longer in use, how long have they been out of service? N/A If tanks are no longer in use, have tanks been abandoned according to DEP? Yes Yes No Yunknown Are tanks registered with DEP? Size of tank(s): N/A Location: NONE KNOWN	Comments: WOODSTOV	'E HOOKUP IN KITCI	HEN, CONDITION U	JNKNOWN AS SELL	ER NEVER USED IT		
The licensee is disclosing that the Seller is making representations contained herein. A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Storage tanks on the property? Yes Yes </td <td></td> <td></td> <td></td> <td></td> <td></td>							
A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No X Unknown If Yes, are tanks in current use? Yes No X Unknown If no longer in use, how long have they been out of service? N/A No X Unknown If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No X Unknown Are tanks registered with DEP? Size of tank(s): N/A No X Unknown Location: NONE KNOWN Size of tank(s): N/A No		SECTION IV	- HAZARDOUS M	ATERIAL	14. A. 13. S.A.		
storage tanks on the property? Image: Yes No No <td< td=""><td>The licensee is disclosing</td><td>that the Seller is makir</td><td>ng representations con</td><td>ntained herein.</td><td></td></td<>	The licensee is disclosing	that the Seller is makir	ng representations con	ntained herein.			
If Yes, are tanks in current use? Yes No X Unknown If no longer in use, how long have they been out of service? N/A No X Unknown If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No X Unknown Are tanks registered with DEP? Yes No X Unknown Age of tank(s): N/A Size of tank(s): N/A No X Unknown Location: NONE KNOWN Size of tank(s): N/A No No	A. UNDERGROUND	STORAGE TANKS	- Are there now, or	have there ever bee	en, any underground		
If Yes, are tanks in current use? Yes No X Unknown If no longer in use, how long have they been out of service? N/A No X Unknown If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No X Unknown Are tanks registered with DEP? Yes No X Unknown Age of tank(s): N/A Size of tank(s): N/A No X Unknown Location: NONE KNOWN Size of tank(s): N/A No No	storage tanks on the prop	erty?		Yes	No X Unknown		
If no longer in use, how long have they been out of service? N/A If tanks are no longer in use, have tanks been abandoned according to DEP? Yes Are tanks registered with DEP? Yes Age of tank(s): N/A Location: NONE KNOWN							
If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No X Unknown Are tanks registered with DEP? Yes No X Unknown Age of tank(s): N/A Size of tank(s): N/A No X Unknown Location: NONE KNOWN Size of tank(s): N/A Size of tank(s): N/A Size of tank(s): N/A							
Are tanks registered with DEP? Yes No X Age of tank(s): N/A Size of tank(s): N/A No X Location: NONE KNOWN No X	•			DEP? Yes	No 🗙 Unknown		
Age of tank(s): N/A Size of tank(s): N/A Location: NONE KNOWN			-		8		
Location: NONE KNOWN				نيــــ			
	•	WN		1-42 -			

Page 3 of 8

PROPERTY LOCATED AT: 4 HEMMING WAY, YORK, ME 03909

Buyer Initials _____ ___

JORT

Seller Initials

PROPERTY LOCATED AT: <u>4 HEMMING WAY, YORK, ME</u> 03909		
What materials are, or were, stored in the tank(s)? N/A		
Have you experienced any problems such as leakage:		No X Unknown
Comments: SELLER HAS NO KNOWLEDGE OF UNDERGROUND ST	ORAGE 1	ANKS
Source of information: SELLER		
B. ASBESTOS - Is there now or has there been asbestos:		
As insulation on the heating system pipes or duct work?	Yes	No X Unknown
In the ceilings?	Yes	No X Unknown
In the siding?	Yes	No X Unknown
In the roofing shingles?	Yes	🗌 No <u>X</u> Unknown
In flooring tiles?	Yes	🗌 No <u>X</u> Unknown
Other: N/A	_ Yes	🗌 No <u>X</u> Unknown
Comments: HOUSE BUILT IN 1989, SELLER HAS NO KNOWLEDGE	OF ASBES	STOS
Source of information: SELLER		
C. RADON/AIR - Current or previously existing:		
Has the property been tested?	X Yes	No Unknown
If Yes: Date: 04/02/2025 By: NORTHCOAST HOME IN	SPECTION	NS
Results: ACCEPTABLE LEVEL- 0.8 PCI/L		
If applicable, what remedial steps were taken? NONE NEEDED		
Has the property been tested since remedial steps?	Yes	X No Unknown
Are test results available?	X Yes	No
Results/Comments: NONE		
Source of information: SELLER, PRE-LISTING INSPECTION		
D. RADON/WATER - Current or previously existing:		
Has the property been tested?	X Yes	🗌 No 📙 Unknown
If Yes: Date: 03/31/2025 By: NELSON ANALYTICAL		
Results: 1400 PCI/L		
If applicable, what remedial steps were taken? N/A		
Has the property been tested since remedial steps?	∐ Yes	<u>X</u> No 📋 Unknown
Are test results available?	X Yes	🗌 No
Results/Comments: UNDER MAINE LIMIT OF 4,000 PCI/L		
Source of information: SELLER, PRE-LISTING INSPECTION		
E. METHAMPHETAMINE - Current or previously existing:	Yes	🗴 No 🖾 Unknown
Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF METHAMPE	TAMINE O	N THE PROPERTY
Source of information: SELLER		
	Initial	
	(Det	
Buyer Initials Page 4 of 8 Seller Ini	tials JVr I	

THOT LIKE I DOCTOR IN THE WIND WALL DOWN WAR US / 05/07	PROPERTY LOCATED	AT: 4 HEMMING WAY,	YORK. ME 03909
---	------------------	--------------------	----------------

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is constructed prior to 1978)	s most commonly found in homes		
Is there now or has there ever been lead-based paint and/or lead-based paint	hazards on the property?		
	nown (but possible due to age)		
If Yes, describe location and basis for determination: <u>N/A</u>			
Do you know of any records/reports pertaining to such lead-based paint/lead-based paint paint/lead-based paint/lead-based paint/lead-based paint/lead-based paint/lead-based paint pa	based paint hazards: 🔲 Yes 🕱 No		
If Yes, describe: N/A			
Are you aware of any cracking, peeling or flaking paint? X Yes No			
Comments: SOME MINOR FLAKING AROUND EXTERIOR DECK AN	D STAIR POSTS		
Source of information: SELLER, PRE-LISTING INSPECTION			
G. OTHER HAZARDOUS MATERIALS - Current or previously existing:			
TOXIC MATERIAL:	Yes No X Unknown		
LAND FILL:	Yes No X Unknown		
RADIOACTIVE MATERIAL:	Yes No X Unknown		
Other: SELLER HAS NO PERSONAL KNOWLEDGE OF HAZARDOU	IS MATERIALS		
Source of information: SELLER			
	1.01		

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the	property	subje	ect to or ha	ave the be	enefit of	any enc	roachments, e	asements, right	ts-of-way, lea	ases, rights of
first	refusal,	life	estates,	private	ways,	trails.	homeowner	associations	(including	condominiums
and P	'UD's) or	restric	ctive cove	nants?				<u>X</u> Y	es 🗌 No	Unknown

If Yes, explain: **ROW OVER PRIVATE ROAD; SEWER EASEMENT MANHOLE** Source of information: **SELLER, PUBLIC RECORD, DEED, PREVIOUS DISCLOSURE**

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes X No Unknown If No, who is responsible for maintenance? UNKNOWN, SELLER HAS NEVER LIVED IN THE HOME Road Association Name (if known): UNKNOWN Source of information: SELLER, PUBLIC RECORD

Buyer	Initial	s _
-------	---------	-----

Initial N/R1 Seller Initials

PROPERTY LOCATED AT: 4 HEMMING WAY, YORK, ME 03909

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:		
Have any flood events affected the property?	Yes	🗴 No 🗌 Unknown
If Yes, explain: N/A		
Have any flood events affected a structure on the property?	Yes	🗴 No 🗌 Unknown
If Yes, explain: <u>N/A</u>		
Has any flood-related damage to a structure occurred on the property?	Yes	🗴 No 🗌 Unknown
If Yes, explain: <u>N/A</u>		
Has there been any flood insurance claims filed for a structure on the		
property?	Yes	🕱 No 🗌 Unknown
If Yes, indicate the dates of each claim: <u>N/A</u>		
Has there been any past disaster-related aid provided related to the property		
or a structure on the property from federal, state or local sources for		
purposes of flood recovery?	Yes	X No Unknown
If Yes, indicate the date of each payment: <u>N/A</u>		
Is the property currently located wholly or partially within an area of special		
flood hazard mapped on the effective flood insurance rate map issued by the		
Federal Emergency Management Agency on or after March 4, 2002?		
If yes, what is the federally designated flood zone for the property indicated	l on that flo	od insurance rate map?
<u>N/A</u>		
Relevant Panel Number: 23031C0669G Year:		(Attach a copy)
Comments: FEMA MAPS SHOW PROPERTY IS NOT IN A FLOOD	ZONE	
	Initial	
Source of Section VI information: SELLER, PUBLIC RECORD Buyer Initials Page 6 of 8 Seller Init	ials MRT	· · · · · · · · · · · · · · · · · · ·
Buyer Initials Page 6 of 8 Seller Initials		
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com		RUST FAMILY TRUST

PROPERTY LOCATED AT: 4 HEMMING WAY, YORK, ME 03909

SECTION VII - GENERAL INFORMATION
Are there any tax exemptions or reductions for this property for any reason including but not limited to:
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?
If Yes, explain: HOMESTEAD EXEMPTION
Is a Forest Management and Harvest Plan available?
Are there any actual or alleged violations of a shoreland zoning ordinance
including those that are imposed by the state or municipality? Yes X No Unknown If Yes, explain: N/A
Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water
filtration system, photovoltaics, wind turbines): Type: NONE KNOWN
Year Principal Structure Built: 1989 What year did Seller acquire property? 2019
Roof: Year Shingles/Other Installed: 2008
Water, moisture or leakage: NONE KNOWN
Comments: NONE
Foundation/Basement:
Is there a Sump Pump? Unknown
Water, moisture or leakage since you owned the property: Yes X No Unknown
Prior water, moisture or leakage?
Comments: SUMP PUMP RUNS AFTER HEAVY RAINS AND/OR SEVERE STORMS
Mold: Has the property ever been tested for mold?
If Yes, are test results available?
Comments: NONE
Electrical: Fuses X Circuit Breaker Other: N/A Unknown
Comments: ELECTRIC PANEL CIRCUIT BREAKERS HAVE BEEN RECENTLY LABELED
Has all or a portion of the property been surveyed? Yes Ves Ves Unknown
If Yes, is the survey available? If Yes Yes Yes Yes Yes
Manufactured Housing - Is the residence a:
Mobile Home
Modular
Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
Comments: <u>NEW PREVENTATIVE PEST CONTROL MAINTENANCE CONTRACT IN PLACE WITH JP PESTS</u>
KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may
have an adverse impact on health/safety: NONE KNOWN; PROPERTY HAS BEEN PRE-INSPECTED
Comments: SELLER HAS NO PERSONAL KNOWLEDGE OF ANY OTHER DEFECTS
Source of Section VII information: Seller, PREVIOUS DISCLOSURE, PUBLIC RECORD Buyer Initials Page 7 of 8 Seller Initials

PROPERTY LOCATED AT: 4 HEMMING WAY, YORK, ME 03909

SECTION VIII - ADDITIONAL INFORMATION

Seller is a Trustee & has never lived in the house. New interior paint in several areas & 1st floor ceiling. New smoke detector/CO2 combos installed & carpets cleaned. Newer garage doors. Skylights are not in working condition & have compromised seals. Bathroom ceiling fans are wired but unplugged & do not vent to the outside. Laundry plug may not be linked to a GFCI. Front walkway is cracked/bumpy & decks have some areas needing paint. Basement window has a small hole in glass.

House has central vac but condition is unknown.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Signed by: John D. Rust, Trustu SELBIZER769924AE RUST FAMILY TRUST	4/23/2025 DATE	John D. Rust, Trustu SELdizERA769924AE JOHN D. RUST, TRUSTEE	4/23/2025 DATE
SELLER	DATE	SELLER	DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
BUYER	DATE	BUYER	DATE



Page 8 of 8



BEALTORS All Rights Reserved. Revised September 2024.

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

National Flood Hazard Layer FIRMette

FEMA

0°38'43"W 43°8'42"N





This map image is void if the one or more of the following mar elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for

unmapped and unmodernized areas cannot be used for

regulatory purposes.